

164	H & P E	HVAC	Women's basketball shower room exhaust							J. Ben							
164	H&PE	HVAC	Replace Hot Water Pump	12,128.11	A/W Mechanical	R0106804	P0149684			J. Ben			11-Oct			Complete	
164	H&PE	Windows	Waterproof Bay windows	\$4,831.50	Atlas	R00107527	P0150856	AE-20180046		D. Williams		7-Jun	29-Jun			Complete	
165	Science	Generator	Perform Load Bank Test, Diagnostic and Repair	1,515.04	Cummins sales and Services	R0105819	P0148992	PP-20180069		D. Steward		23-Feb	27-Mar			Complete	
165	Science	Plumbing system	Replace restroom faucets							J. Ben							
165	Science	Generator	Emergency Generator Repair							D. Steward							
165	Science	Electrical	Upgrade lighting automation controls							R. Fontenot						Awaiting Quotes	
165	Science	HVAC	Repair VAV box hot water coil	3,905.00	American Mechanical Services	R0107729	P0150427	CP-20181061		J. Ben			11-Oct			Complete	
165	Science	Access Control System	Repair Door Retractable Latches	8,196.52	Simplex Grinnell, LP	R0108337	P0151055		F. Holts			14-Jul	23-Aug			Complete	
165	Science	Sprinkler Deficiencies	Install compliant exterior shell access ladder	5,371.00	Simplex Grinnell, LP		P0150720		F. Holts			14-Jul	23-Aug			Complete	
165	Science	Sprinkler Deficiencies	Install locking device on drain valve	1,548.00	Simplex Grinnell, LP		P0150720		F. Holts			14-Jul	23-Aug			Complete	
165	Science	Sprinkler Deficiencies	Install screen on overflow pipe		Simplex Grinnell, LP				F. Holts								
165	Science	Sprinkler Deficiencies	Interior cleanout of sediment Fire Tank	2,941.00	Simplex Grinnell, LP		P0150720		F. Holts							Complete	
165	Science	Sprinkler Deficiencies	Deficiencies						F. Holts								
165	Science	Fire Pump	Replace faulty equipment from FP Inspection	4,194.84	Simplex Grinnell, LP		P0150721		F. Holts			12-Jul	20-Sep			Complete	
165	Science	Phoenix System	Repair/calibrate Phoenix Systems	207,042.00	Vicon		PO146916					15-Mar	28-Mar			Complete	
TO 1	Tierwester Oaks	Fire Sprinkler System	Replace painted heads	\$2,632	Simplex Grinnell, LP		PO150793		F. Holts			12-Jul				95% Complete	
TO 2	Tierwester Oaks	Fire Sprinkler System	Replace check valves	\$2,078	Simplex Grinnell, LP		PO150799		F. Holts			12-Jul	5-Dec			Complete	
UC 1	University Courtyard	Fire Alarm System	Smoke detectors not reporting	\$476	Simplex Grinnell, LP		PO150789		F. Holts			12-Jul	3-Oct			Complete	
UC 1	University Courtyard	Fire Sprinkler System	Replace painted heads	\$5,495	Simplex Grinnell, LP		PO150791		F. Holts			12-Jul	5-Dec			Complete	
UC 2	University Courtyard	Fire Sprinkler System	Replace painted heads	\$7,456	Simplex Grinnell, LP		PO150792		F. Holts			12-Jul	5-Dec			Complete	
UC1	University Courtyard	Fire Sprinkler System	Repair Nebo ball valve, repair leak	\$2,021	Simplex Grinnell, LP		PO150790		F. Holts			12-Jul	5-Dec			Complete	
				3,528,631.04	2,035,096.53												