



161	G5B	Maintenance	Lift jacks for motor coach bus	26480.00	Arnold Oil Equipment	RO10539	PO151995	PP-20181935	D. Steward		8-Aug	23-Aug	Complete
161	G5B	Vehicle	12 Passenger Van with luggage space Ford Transit	29916.50	Sisbee Ford	R010345	PO152706	PP-20181934	D. Steward		20-Aug	20-Feb	Complete
161	G5B	Maintenance	MCI bus diagnostic computer	3975.96	Motor Coach Industries	R0108536	PO151361	PP-20181932	D. Steward		2-Jul	1-Nov	Complete
161	G5B	Ego, club car, Yamaha	Replace facility dept. utility carts	32604.00	E-Z-Go Testron/Cushman	R0108537	PO151360	PP-20181931	D. Steward		12-Jul	29-Aug	Complete
161	G5B	Utilitytruck Carts	SUS-L-2 Summit Utilitytruck	43240.00	HEB/Parkway Systems	R0108538	PO151361	PP-20181932	D. Steward		12-Jul	12-Oct	Complete
161	G5B	Maintenance/Staff Equipment	Maintenance Staff Equipment	30000.00			PO149971		M. Young			19-Nov	Complete
161	G5B	3 Leased Police Vehicles	Unmarked Subs	35100.00			PO149971		M. Young			19-Nov	Complete
161	G5B	6 EZ-GO Police golf carts	Golf Carts	44000.00			PO148747		M. Young			19-Nov	Complete
161	G5B	3 Senequa's	SE-3 Sprinkler	39000.00			PO148711		M. Young			19-Nov	Complete
161	G5B	Dispatch Renovations	Remodeling	28786.00	Nash Industries	R0108764	PO151471	AE-20180043	D. Williams		19-Jul	16-Oct	Complete
161	G5B	Dispatch Renovations	Data Management	12735.00	PCS Telcom	PO151927	AE-20180043		D. Williams		29-Aug	1-Nov	Complete
161	G5B	Dispatch Renovations	Surveillance	8525.00	Zycom	PO152368	AE-20180043		D. Williams		17-Sep	1-Nov	Complete
161	G5B	15 Police Sedans	Marked						M. Young				
161	G5B	3 Police SUVs	Marked						M. Young				
161	G5B	Uniforms	Police/Security Uniforms						M. Young				
161	G5B	Sprinkler Replacement	Replace Faulty/Damaged Sprinkler Heads	8372.00	Simplex Grinnell, LP	R0107088	PO150723		F. Hobbs		12-Jan	19-Jul	Complete
161	G5B	Sprinkler Deficiencies	Repair the Fire Department Connection	1180.60	Simplex Grinnell, LP		PO150723		F. Hobbs		12-Jul	12-Jul	Complete
163	Technology Fountain	Electrical	Equipment replacement						E. Bennett				Awaiting Quotes
163	Technology	Sprinkler Deficiencies	Adjust & Lubricate clay valve, replace suction gauge	920.00	Simplex Grinnell, LP	R0108497	PO151138		F. Hobbs		14-Jul	22-Aug	Complete
163	Technology	Fire Pump	Updates as part of an inspection report	920.00	Simplex Grinnell, LP		PO150704		F. Hobbs		12-Jul	4-Oct	Complete
164	H & P E	HVAC	Men's basketball shower room exhaust						J. Ben				
164	H & P E	HVAC	Women's basketball shower room exhaust						J. Ben				
164	H&PE	HVAC	Replace Hot Water Pump	12128.11	A/W Mechanical	R0106894	PO149684		J. Ben			11-Oct	Complete
164	H&PE	Windows	Waterproof Bay windows	4831.50	Atlas	R00107527	PO150856	AE-20180046	D. Williams		7-Jun	29-Jun	Complete
165	Science	Generator	Perform Load Bank Test, Diagnostic and Repair	1515.04	Cummins sales and Repair	R0148992	PO148992	PP-20180069	D. Steward		23-Feb	27-Mar	Complete
165	Science	Plumbing system	Replace restroom faucets	3905.00	American Mechanical Services	R0107739	PO150477	CP-20181061	J. Ben			11-Oct	Complete
165	Science	HVAC	Repair VAV box hot water coil	8196.52	Simplex Grinnell, LP	R0108337	PO151055		F. Hobbs		14-Jul	23-Aug	Complete
165	Science	Sprinkler Deficiencies	Install compliant exterior shell access ladder	5371.00	Simplex Grinnell, LP		PO150720		F. Hobbs		14-Jul	23-Aug	Complete
165	Science	Sprinkler Deficiencies	Install locking device on drain valve	1548.00	Simplex Grinnell, LP		PO150720		F. Hobbs		14-Jul	23-Aug	Complete
165	Science	Sprinkler Deficiencies	Install screen on overflow pipe		Simplex Grinnell, LP				F. Hobbs				Complete
165	Science	Sprinkler Deficiencies	Interior cleanup of sediment Fire Tank	2941.00	Simplex Grinnell, LP		PO150720		F. Hobbs				Complete
165	Science	Sprinkler Deficiencies	Deficiencies						F. Hobbs				Complete
165	Science	Fire Pump	Replace facility equipment from EP Inspection	4184.84	Simplex Grinnell, LP		PO150721		F. Hobbs		12-Jul	20-Sep	Complete
165	Science	Phoenix System	Repair/calibrate Phoenix Systems	207042.00	Vicon		PO146916		F. Hobbs		15-Mar	28-Mar	Complete
TO 1	Tierwester Oaks	Fire Sprinkler System	Replace painted heads	2632.00	Simplex Grinnell, LP		PO150793		F. Hobbs		12-Jul	28-Jan	Complete
TO 2	Tierwester Oaks	Fire Sprinkler System	Replace check valves	2078.00	Simplex Grinnell, LP		PO150799		F. Hobbs		12-Jul	5-Dec	Complete
UC 1	University Courtyard	Fire Alarm System	Smoke detectors not reporting	428.00	Simplex Grinnell, LP		PO150789		F. Hobbs		12-Jul	3-Oct	Complete
UC 1	University Courtyard	Fire Sprinkler System	Replace painted heads	1495.00	Simplex Grinnell, LP		PO150791		F. Hobbs		12-Jul	5-Dec	Complete
UC 2	University Courtyard	Fire Sprinkler System	Replace painted heads	7456.00	Simplex Grinnell, LP		PO150792		F. Hobbs		12-Jul	5-Dec	Complete
UC1	University Courtyard	Fire Sprinkler System	Repair Neko ball valve, repair leak	2021.00	Simplex Grinnell, LP		PO150790		F. Hobbs		12-Jul	5-Dec	Complete
				3,051,591.04	2,482,974.53								